

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS No. VA-1209

HABS  
VA,  
82-LEX-V,  
5-

Thorn Hill  
SW of Lexington, off VA Rt. 251  
Lexington vicinity  
Rockbridge County  
Virginia

Jack E. Boucher, photographer

April 1971

VA-1209-1	EAST FRONT FROM NORTHEAST
VA-1209-2	EAST FRONT FROM SOUTHEAST
VA-1209-3	EAST PORTICO FROM NORTHEAST
VA-1209-4	ENTRANCE STEPS AND FRONT DOOR, EAST FRONT
VA-1209-5	GENERAL VIEW, WEST REAR
VA-1209-6	DETAIL, WEST PORCH
VA-1209-7	WINDOW, FIRST FLOOR, SOUTH OF EAST FRONT ENTRANCE
VA-1209-8	STAIRS AND DOOR, FIRST FLOOR HALL
VA-1209-9	BROKEN PEDIMENT OVER DOOR, FIRST FLOOR HALL
VA-1209-10	CORNICE DETAIL, FIRST FLOOR HALL
VA-1209-11	SOUTH ROOM, FIRST FLOOR, GENERAL VIEW
VA-1209-12	SOUTH ROOM, FIRST FLOOR, MANTEL
VA-1209-13	NORTH ROOM, FIRST FLOOR, GENERAL VIEW